#226

SDMS Document ID

1051994

Meagan Redfern

OCARS_Pro@uncc.org

From: Sent: Thursday, October 13, 2005 1:00 PM

To:

Meagan Redfern

UNCC EMLCFM 2005/10/13 #00227 A0400909-00A NORM NEW Subject:

EMLCFM 00227 UNCCa 10/13/05 01:00 PM A0400909-00A NORM NEW STRT LREQ

Ticket Nbr: A0400909-00A

Original Call Date: 10/13/05 Time: 01:00 PM Op: MRE

: 10/17/05 Time: 11:59 PM Meet: N Extended job: N Locate By Date

State: CO County: DENVER City:

3454 Street: FRANKLIN ST

Grids: 03S068W26N* Legal: Y

Lat/Long: 39.766437/-104.969308 39.766437/-104.967515

: 39.763825/-104.969308 39.763825/-104.967515

Type of Work: SOIL EXCAVATION Exp.: N

Boring: N

Location: LOC ENTIRE LOT*ACCESS OPEN*INDIVIDUAL STRUCTURE *LOCATE TO

INCLUDE ALL

: CITY PROPERTY AND EASEMENTS

Company: PROJECT RESOURCES INC. Type: OTHR

Caller : MEAGAN REDFERN Phone: (303) 487-0377 Phone: (303) 487-0377

Alt Cont: AMY JAMES Email: MREDFERN@PROJECTRESOURCESINC.COM

Done for: ARMY CORPS OF ENGINEERS/EPA

Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA CMSND00= COMCAST - NORTH

DENVER

Members DNSCH1 = DENVER PUBLIC SCHOOLS ICGTL3 = ICG

TELECOMMUNICATIONS

Members PCKVEL = XCEL ENERGY-ELEC TRANSM PCNDU0 = XCEL ENERGY-NORTH

Members PSND14 = XCEL ENGY--APPT SCHEDULE QLNCND0= QWEST LOCAL

NETWORK

Members QLNCND1= QWEST LOCAL NETWORK TWTEL1 = TIME WARNER

Members WCG01 = WILTEL COMMUNICATION

You are responsible for contacting any other utilities that are not

listed above

including the following tier 2 members not notified by the center:

DNVH20 DENVER WATER DEPT (303) 628-6666 DNVPR1 DENVER PARKS & REC. (303)458-4839

DTEO01 DNVR TRAFFIC ENG OPERAT. (720)865-4001

WWMG01 WASTEWATER MGMT DIVISION (303)446-3744 This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 3454 Franklin Street

INPUTS	Variable	Units	House
General	Mixing depth in yard	cm	2.54
	Mixing depth in yard	inches	1
	Soil density	g/cm3	2.5
	RBC in soil	mg/kg	400
	Bkg in clean fill	mg/kg	50
	-	-	Small
House-specific	Area of the exposure unit	m2	88.07208
-	Area of the exposure unit	ft2	948
	Concentration of lead in paint	mg/cm2	21.1
	Area of peeling paint	m2	1.858061
	Area of peeling paint	ft2	20
COMPUTATIONS	S		
	Mass of lead from paint	mg	3.9E+05
	Volume of soil	cm3	2.2E+06
	Mass of soil	kg	5.6E+03
	Incremental concentration	mg/kg	70.1
	Maximum acceptable area of p	•	9.3
	Maximum acceptable area of p		99.8
DECISION			ок

#226

LeamBased Paint Qualification Calculations

Property ID	Positive XRF Readings	SF of Peeling Paint	Comments
226	784	10	
]	785	8	
	800	1	
	801	1	
	Total SF of Peeling Paint	20	Highest XRF Reading Detected 21.1

1 6/28/2006



Daily Quality Control Report VB/I-70

Lead Based Paint Assessment

Property Location 3454 Famelia

Type and Location of Tests Performed and Results

Type and	d Location of	i ests Perio	rmed and .	Kesults				
Property ID	XRF Reading	Lead POS.	Result NEG.	Direction	Location of Result / Condition	SQ. Feet	Color	Substrate
226	78'3		0.30	W	LATTICE / Chippen		BROUX	Wood
	784	4.0		w	SIDING CONTROL	2/x5'	TAU	wasn
	785	18.1		W	(shingle / shake) cracken	1'x8'	TAN	wood
	78b	1.7	<u> </u>	w	FASCIA / INTACT		BROWN	600k
	787		0.00	w	DOWNSMOT / THRET		BROWN	Teel
	788		0.9	w	WINDOW FRAME / DEDTING		BROWN	wo
<u></u>	789		0.03	N.	EXTERDS WAS INTERT		TAN	BRICK
L	792	9.0		N.	SOFFIT /INTACT		TAN	WOOD
	793		0.4	N	WINDOW FARMS DOSKING		BROWN	woos
	794		0.0	N,	FOUNDATION WALL CAD PROPING		BEAUT	CONCRETE
	795	4,6		E	FASCIA INTACT		BROWN	WOOD
	796	9,1			FASIA TNIACT		BROWN	W 000
	797		0.00	E,	Upper level window FRAME IN	rer_	BROWN	wood
	798	13,4		E,	Shingle Shake INTACT		TAN	woon
<u> </u>	799		0.05	€.	WALL STUCCO (INTACT		TAN	STUCCO
	800	1.5		E.	3" STEEL DIDE / Chippe		TAN	sty steel
	801	1.5		E.	Sot. lower level winnow FL	Aug 2'X2'	BROWN	mode
				ļ	Chippen		<u> </u>	
	ļ	ļ						
1	ļ						 	
V		<u> </u>				İ	<u> </u>	

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.

Contractor's Quality Control Representative

Chephole

Date: 06-20-06



Daily Quality Control Report VB/I-70

Date: 6/2012-06

Lead Based Paint Assessment

Property Location 3454 Franklin


Type and Location of Tests Performed and Results

			10001100			
			Direction	Location of Result / Condition SQ. Feet	Color	Substrate
		NEG.				
761	1.1			CHIBRATION		
762	1.2			CALIBRATION		
763	1.2			CALIBARTION		
764		0.06	5	SW Brick Wall / Intact	Tan	Brick
765	8.1		ŞW.	SW window Frame / Intact	Tan	wood.
766		0.08	SW		Tan	wood
767		0.21	4		Tu-	200d
768		0-01	5	Brick Foundation cappel	tan	cement
764		0.00	SE	Window Frame THACT	Tan	wood
770		0.01	SE	Brick Wall - Intact	tan	brick
771	3.7		5		TAN	wood
772	6.6		8	Sofit - Intact	tan	wood
773	2.2			Cedar Shringle - Intact	+00	wood
725		5,01	5	BUTTER INTET	THEO	STEEL
776	9,9		ω		tan	سامان
フフフ	æ	0.00	7	Doorframe - peeling	White	wood
778		0.00	ω	Stucco Wall- Clacked	tan	5+4668
779		0.60.4		porch column-cracked	tan	wood
780	2/./		W	Douch cooling ContenTATAT	TALIN	WOON
781	12.7		·w	TRM INTACT		
782		0.12	W	WASTULLO INTOLY	TAN	STUCE
	XRF Reading # 761 762 763 764 765 166 767 768 769 770 772 773 775 776 777 778 779 780 780	XRF Reading Lead # POS. 761 /.1 762 /.2 763 /.2 764 7.5 765 8.1 166 767 7168 7169 770 772 6.6 7772 6.6 7774 2.2 775 726 9.9 777 2.7 780 2/.1 781 /2.7	XRF Reading Lead Result # POS. NEG. 761 J.1 NEG. 762 J.2 1.2 763 J.2 0.06 764 0.06 0.08 765 8.1 0.08 767 0.08 0.01 768 0.00 0.01 770 3.7 0.01 771 5.6 0.01 773 2.2 0.01 775 0.01 0.01 776 9.9 0.00 778 0.00 0.00 780 2/./ 0.00 781 /2.7 0.00	# POS. NEG. Direction 761 /.1 762 /.2 763 /.2 764 0.06 5 715 8.1 5 166 0.08 5 7167 0.01 5 7169 0.01 5 770 0.01 5 770 5 772 6.6 5 773 2.2 5 775 7.0 5 776 9.9 778 0.00 780 2/./ 781 /27	XRF Reading Lead Result POS. NEG. 761 761 762 763 764 765 764 765 764 765 766 767 768 767 767 768 767 768 769 769 769 769 760 767 768 769 769 769 760 760 760 760 760 760 760 760 760 760	XRF Reading Lead Result Direction Location of Result / Condition SQ. Feet Color 761 1.1 CALIDARION CALID

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.

Contractor's Quality Control Representative___

Ch plum



(21+12)(46+12)-(21)(46)= (33)(58)-966=[948]



999 18th STREET - SUITE 300 DENVER, CO 80202-2466 http://www.epa.gov/region08

January 26, 2006

Mr./Ms. Joseph And Marcella Ferrer 4540 Sherman Street Denver, CO 80216

Dear Mr./Ms. Joseph And Marcella Ferrer,

This letter certifies that soils on the property at 3454 Franklin Street in Denver, Colorado, have been remediated in accordance with the U.S. Environmental Protection Agency's (EPA) Record of Decision for the Vasquez Boulevard and Interstate 70 Superfund Site (VB/I-70), Operable Unit 1, signed by EPA on September 25, 2003. The required work was accomplished in accordance with EPA approved work plans. The remediation successfully addressed the health risks associated with exposure to arsenic and lead in soils at this property.

The clean-up action conducted by the EPA and the U.S. Army Corps of Engineers (USACE) addressed residences where the soil concentrations of lead and/or arsenic exceeded the action levels of 400 parts per million (ppm) and/or 70 ppm, respectively. The clean up consisted of excavation of the top 12 inches of soil at the listed property. The excavated area was replaced with clean soils.

In order to assure that your property remains protected from lead contamination, it may be necessary to maintain the exterior of your home to prevent any chipping or peeling paint from being deposited in your yard. Very old paint (from 1978 or before) could contain lead contaminates. An EPA representative will be contacting you to schedule a lead based paint assessment of the exterior of your home. EPA will provide for the initial abatement of lead based paint if necessary.

If you require more specific information concerning the clean-up of your property, please contact me at U.S. EPA (8EPR-SR), 999 18th Street, Suite 300, Denver, CO 80202-2466, Attn: Victor Ketellapper, or 303-312-6578, or Pat Courtney at 303-312-6631.

Sincerely,

Victor Ketellapper

Project Manager



REGION 8
999 18th STREET - SUITE 300
DENVER, CO 80202-2466
http://www.epa.gov/region08

26 de Enero de 2006

Señor /Señora Joseph And Marcella Ferrer 4540 Sherman Street Denver, CO 80216

Estimado(a) Señor/Señora Joseph And Marcella Ferrer,

Este carta certifica que tierra en el propiedad 3454 Franklin Street en Denver Colorado, ha sido remediado de acuerdo con la U.S. Environmental Protection Agency's (EPA) Recuerdo de Decisión para el Vasquez Boulevard y Interstate 70 Superfund Site (VB/I-70), Operable Unit 1, Firmado por EPA en September 25, 2003. El trabajo requerido era realizado de acuerdo con EPA confirmado plan del trabajo. La remediación eliminado con éxito los riesgos asociados con la exposición a arsénico y plomo en la tierra en su propiedad.

La acción de limpieza conductazo por EPA y el U.S. Army Corps of Engineers (USACE) dirigido a residentes donde las concentraciones de plomo y/o arsénico en la tierra excedido el nivel de acción de 400 partes por millón (ppm) y/o 70 ppm respectivamente. La limpieza consistido de la excavación de la primera doce pulgadas de tierra de la propiedad listado. El área excavado era reemplazado con tierras limpias.

Para asegurar que su propiedad permanece protegido de la contaminación de plomo, podría ser necesario a mantener el exterior de su hogar a prevenir cualquier astilla o la pintura a se descascara y deposita en su propiedad. Pintura muy viejo (de 1978 o antes) podría contener contaminantes de plomo. Un representante de EPA les contactará a hacer una reunión para una evaluación de pintura con plomo para la exterior de su hogar. EPA provendrá la primera rebaja de pintura basado con plomo si sea necesario.

Si quisiera mas información especifica en relación de la limpieza de su propiedad, por favor contáctame en U.S. EPA (8EPR-SR), 999 18th Street, Suite 300, Denver, CO 80202-2466, Attn: Victor Ketellapper, or 303-312-6578, or Pat Courtney at 303-312-6631.

Sinceramente,

Victor Ketellapper Gerente del Proyecto

Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name: Joseph of Suiter

Phone: 303-192-5893

JOSE MANUEL & MARCELLA FERRER

Addresses of Properties covered by this Agreement:

Address: 4540 Sherman 51 80716

Address: 720-981-3703-Marcella S

home #

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed. The Grantor will have an opportunity to review and approve the planned soil removal and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc:
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save:
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

	☐ I do not grant access to my properties
June 00-26.05	· • • • • • • • • • • • • • • • • • • •
Date Date	Signature Date

☐ My property has a working sprinkler system that will need to be replaced.



REGION 8
999 18th STREET, SUITE 300
DENVER, CO 80202-2466
Phone 800-227-8917
http://www.epa.gov/region08

Ref: 8EPR-SR

August 12, 2005

JOSE MANUEL & MARCELLA FERRER
2834 CURTIS ST 4540 Scherman DENVER CO 80205—80216

RE: 3454 FRANKLIN ST

Dear JOSE MANUEL & MARCELLA:

The United States Environmental Protection Agency (EPA) has tested your property for arsenic and lead soil contamination as pert of the Vasquez Boulevard/Interstate 70 (VB/I-70) Superfund Site.

Concentrations of Arsenic and/or lead found in your soil are high enough for your property to qualify for the removal action EPA is performing this year.

ADDRESS	EPA Cleanup Level
Lead	
423 parts per million (ppm)	above 400 ppm
Arsenic	
13 ppm	above 70 ppm
423 parts per million (ppm) Arsenic	••

EPA would like to remove the top layer of soil from your yard and replace it with clean soil. EPA will then re-landscape your yard to a condition similar to original. All work will be performed by EPA for free. EPA requires your consent to proceed as soon as possible. An Access Agreement that will allow the EPA to perform the soil removal work accompanies this letter. I strongly encourage you to sign this agreement and mail it back to the following address:

US EPA – VB/I-70 Project Site
Attention: Victor Ketellapper
10 East 55th Avenue
Denver, Colorado 80216

Your property will be scheduled for soil removal provided we promptly receive the signed Access Agreement with a telephone number where you can be contacted. EPA will coordinate the soil removal activity with you to reduce any inconvenience to you. Upon completion of the cleanup, EPA will issue a letter stating that your property has been cleaned and that no further action is necessary.

Once the attached access agreement has been received, representatives of EPA will contact you to discuss the removal of contaminated soil from your property. In the meantime, if you have further questions regarding the removal of contaminated soil at your property, please contact us at (303) 487-0377.

Sincerely,

Victor Ketellapper Remedial Project Manager United States Environmental Protection Agency (US EPA)



REGION 8 Victor Ketellapper Phone 800-227-8917 http://www.epa.gov/region08

CONSENT FOR ACCESS TO PROPERTY

Name: JOSE MANUEL & MARCELLA FERRER (or current property

owner)

Location of Property: 3454 FRANKLIN ST

I consent to officers, employees, and authorized representatives of the United States Environmental Protection Agency (EPA) entering and having continued access to the above referenced property for the purpose of taking samples of soil on the Site.

I realize that these actions are undertaken pursuant to EPA's response and enforcement responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA or Superfund), 42 U.S.C. § 9601 et seg.

303-292-9893

Phone Number

plesse un send MAT



Agencia de Protección del Medio Ambiente de los Estados Unidos **REGION 8** Victor Ketellapper Phone 800-227-8917 http://www.epa.gov/region08

CONSENTIMIENTO PARA ENTRAR EN LA PROPIEDAD

Nombre del Dueño de la Propiedad: JOSE MANUEL & MARCELLA FERRER

Dirección de la Propiedad: 3454 FRANKLIN ST

Permitiré al personal de la Agencia de Protección del Medio Ambiente de los Estados Unidos(EPA) y a sus representantes autorizados entrar y tener acceso continuo a la propiedad arriba citada con el propósito de tomar muestras de suelo en el lugar.

Yo entiendo que estas acciones son adelantadas por EPA como parte de sus responsabilidades, de acuerdo con las disposiciones de la Respuesta Ecológica Integral, Ley de Responsabilidades y Compensaciones (Comprehensive Environmental Response, Compensation and Liability Act - Superfund) 42 U.S.C. s. 9601, et seq.

Nombre y apellidos	
Número de Teléfono	
Firma	Fecha

URS OPERATING SERVICES

1099 18TH STREET SUITE 710 DENVER, COLORADO 80202-1908

TEL: (303) 296-3523 FAX: (303) 291-8296

September 2, 2004

JOSE MANUEL & MARCELLA FERRER (or current owner) 2834 CURTIS ST DENVER CO 80205

SUBJECT:

START2, EPA Region VIII, Contract No. 68-W-00-118, TDD No. 0305-0005

Vasquez Boulevard and I-70 Soil Sampling at 3454 FRANKLIN ST in Denver,

Colorado

Dear JOSE MANUEL & MARCELLA FERRER (or current owner):

U.S. Environmental Protection Agency (EPA) is attempting to sample the soil at all properties in your neighborhood as part of the Vasquez Boulevard and I-70 Superfund Site. URS Operating Services, Inc. has been directed by EPA to conduct this sampling. The results of the soil sampling will be used to determine if lead and arsenic are present at levels that pose a threat to human health. The EPA records indicate that your property at 3454 FRANKLIN ST has not been sampled.

We are requesting your permission for the EPA to collect samples of soil from your property. Please sign the access form that is enclosed with this letter and return it to me in the enclosed addressed and stamped envelope.

You may be aware the EPA has sampled the soil at some properties in your neighborhood. The majority of yards sampled have low levels of lead and/or arsenic. On those properties that are found to have elevated levels of lead and/or arsenic in the soils, EPA will remove and replace the contaminated soil with clean soil. Once the soil has been replaced, the landscaping will be restored by EPA. You may have seen EPA conducting this work in your neighborhood. Please note that there is no cost to the homeowner for this service.

If you have any general questions regarding the Vasquez Boulevard and I-70 Superfund Site or the access agreement, please contact one of the following EPA representatives: Victor Ketellapper (303-312-6578) or Pat Courtney (303-312-6631). If you have any questions about this sampling, please call me at 303-291-8248.

Very truly yours,

URS OPERATING SERVICES, INC.

Anne Hellie Geologist

cc:

T. F. Staible/UOS

(w/o attachment)

File/UOS

1099 18TH STREET SUITE 710 DENVER, COLORADO 80202-1908

TEL: (303) 296-3523 FAX: (303) 291-8296

Septiembre 2, 2004

JOSE MANUEL & MARCELLA FERRER (o actual propietario) 2834 CURTIS ST DENVER CO 80205

TEMA:

START2, EPA Region VIII, Contract No. 68-W-00-118, TDD No. 0305-0005

Muestreo de suelos en la propiedad 3454 FRANKLIN ST en Vásquez Boulevard y I-70,

en Denver, Colorado

Apreciado(a) JOSE MANUEL & MARCELLA FERRER (o actual propietario):

La Agencia para la Protección del Medio Ambiente de los Estados Unidos (EPA) esta trabajando en el muestreo de suelos de todas las propiedades en su vecindario como parte del proyecto "Superfund" Vásquez Boulevard y I-70. URS Operating Services, Inc. ha sido contratado por EPA para realizar este muestreo. Los resultados del muestreo serán utilizados para determinar la posible presencia de plomo y arsénico y si los niveles de concentración son amenazantes para la salud de personas. Los archivos de EPA indican que su propiedad 3454 FRANKLIN ST no ha sido muestreada.

Nosotros estamos solicitando su permiso para que el personal de EPA pueda colectar muestras de suelo de su propiedad. Por favor firme la forma que se anexa a esta carta "Consentimiento para entrar en la propiedad" y regrésemela en el sobre que se adjunta (este ya tiene la dirección y estampilla)

Usted se puede haber dado cuenta que EPA ha muestreado muchas de las propiedades en su vecindario. La mayoría de los patios muestreados tienen bajos niveles de plomo y/o arsénico. En las propiedades que resulten con niveles elevados de plomo t/o arsénico, EPA reemplazará el suelo contaminado con suelo limpio. Tan pronto como el suelo sea reemplazado, el jardín sera restaurado por EPA. Usted puede haber visto a EPA adelantando trabajo similar en su vecindario. Por favor, note que no hay ningún costo por este servicio para el propietario.

Si usted tiene alguna pregunta general sobre el proyecto "Superfund" Vásquez Boulevard y I-70 o respecto al "Consentimiento para entrar en la propiedad", por favor llame a EPA al teléfono 303-312-6596. Si usted tiene alguna pregunta acerca de este muestreo por favor contacte a Mario-Mejía-Navarro al teléfono 303-291-8204.

Sinceramente,

URS OPERATING SERVICES, INC.

Anne Hellie Geóloga


cc:

T. F. Staible/UOS

(w/o attachment)

File/UOS

Anne Hellie



Real Property Records

Date last updated: Friday, August 26, 2005

© Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

View Map/Historic District Listing for this Property Link to property tax information for this property Link to property sales information for this neighborhood Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential Parcel: 0226229005000

> Name and Address Information Legal Description

FERRER, JOSE MANUEL & MARCELLA W 68 1/2 FT OF L 2 BLK 5

FORDS ADD 2834 CURTIS ST RESIDENTIAL **DENVER, CO 80205**

> Tax District Property Address:

3454 FRANKLIN ST **DENV**


Assessment Information


	Actual	Assessed	Exempt	Taxable
Current Year				
Land	10600	840		
Improvements	156100	12430		
Total	166700	13270	0	13270
Prior Year				
Land	7600	610		
Improvements	154200	12270		
Total	161800	12880	0	12880

Style: 1 1/2 Story

Reception No.:

Year Built: 1890 Recording Date: // Building Sqr. Foot: 1,401 Document Type:





Property Check-List

Yes/No

1. No Sprinkler System?

2. No Basement Photos?

3. ____ Photos of Water Meter?

4. All 3 Signatures?

5. yes Number of Trees? 3

6. Approximate Voucher Size?

7. Les Are all trees and bushes clearly labeled on the map?

8. Les Clotheslines marked and is it removed or replaced?

9. <u>no</u> House accessible for equipment?

10. Ues Owner clear of everything they will need to remove?

11. <u>ues</u> Owner clear the dates when we call him are approximate?

12. Les A second walk through done on the property to double check the map by the individual who did the video/photos?



Property Access Checklist

Property ID: 226		_	STARTED	ON:/_/_ ON:/_/_
Property Address: 3454 Amplin		□ work	COMPELTED	ON://
I Description	<u></u>	December D	4	
Property Owner: Jose and Max Mailing Address:		Property R Home Phor		
Mailing Address: 3even	V	Fax:	ie:	
		Cell/Pager:		
Home Phone:			Information:	
Fax:				
Cell/Pager:				
<u> </u>	 · · · ·	<u> </u>	······································	
Notification Letter	Sent:	//_	Ву:	
☐ Access Agreement	Signed:	_//	By:	
Restoration Agreement	Signed: 8	131105	By: Marcella	Lever
Topsoil Sampling (if applicable)	/	_/	Ву:	
☐ Disposal Sampling (if applicable)	'		By:	
Garden Sampling (if applicable)	//		By:	
Utility Clearance	Called:	//_	By:	
☐ Video/Photos (Before)	On: 8 /	31/05	By: R. Kanin	M. Joroler
☐ Video/Photos (During)	On:/		By:	
☐ Video/Photos (After)	On://		By:	
☐ Video/Photos (30-Day)	On://		Ву:	
☐ Property Completion Agreement	Signed:	_//	By:	
☐ Final Report	Issued://		Ву:	
Air Monitoring (as applicable)				
	//_	By:		
Results:		<u> </u>		
☐ Community ☐ Crew On:	//_	By:	***************************************	
Results:		<u>.</u>		
Community Crew On:	//_	By:		
Results:				



Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 226	
Property Address: 3464 Alanklin	
Owner: Jose and Margalla Gerrer	
Phone: Jano - 3) 292 - 9893 Novice D) 981-3703	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Carpit, tois, Jurniture, brayles,
I Item: \ // / \
trash cars vill buckets plastic
Item:
side any floortone or decorative rock
Item:
hores.
Item:
Item:
ftem:
Item:



Item:

Items To Be Removed By Contractor During Remediation And Not Replaced (Use additional sheets as necessary)

Item:
Item:
Item:
Item:
Item:
Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)
tem: Jenes (if any) for access
Clothesline
Item:
Item:
Item:
item:



Landscape Inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	155	Square Feet	
Number of trees > 2 inch trunk diameter	3		
Number of trees < 2 inch trunk diameter			
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	no Apkr Ayatum		Zones:
Number of and total size of all gardens / flower beds.	# Of Beds:		Ft ² Of Beds:
Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft ² Of Gardens:



Project Resources Inc.

ltem	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft ² Of Beds To Be Replaced With Certificate: 3 FB's 1x15; 1x9; 1x4
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be placed by the contractor.	NIA	Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	352	SF	Total Ft ² Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Fr ² :	SF	Sod: 133
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch:	SF	Red:



Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock:	SF	Large:35 Medium: Small (pea gravel): Driveway Gravel:
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover:		

	Additional Comments / Instructions:
	•
·	
	,
	·



	Additional Comments	Instructions Continued:	
:			
}			
		·	
pre-existing damage.	Owner does not want PRI to By checking this box PRI uding foundation cracks or fis	is not responsible for a	ation walls and possible ny damage done to the
I agree	I do not agree	agree	I do not agree
Owner's Signature	Jener 8/31/05	Contractor's Signatu	Joweler 8-31-05 Date



Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID:		
Property Address: gust Alax Plin		Α
Owner: Joseph & Marcella Ser	دراه	acespl
Phone: 720-981-3703 (Marcella-h	one)	303-292-9593
Restoration Items in Question:	cell 3(3 995-5952
Item:		
item:		·
item:		
Item:		·
item:		
item:		
Additional Comments:		
	•	
• .		
•		
I agree restoration is completed, except as noted		
☐ I do not agree restoration is completed -		
I agree that the sprinkler system is working properly following reinstallation by contractor		
Plantler Tener "/11/05	amy Oa	ma 11/10/05
Owner's Signature Date	Contractor's Signatur	e Date





U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Joesph & Marcella Ferrer		
Property Address	3454 Franklin St.		
Property Identification Number	226		

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)	28	\$ 2.50	\$70
Trees	0	\$50.00	\$0
Itemized shrubs/bushes	0	\$12.00	\$0
Total			\$70.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of \$70.00 has been received by the owner in the form of a replacement certificate, #15388, to be utilized at Paulino's Gardens, 6300 N. Broadway, Denver, CO 80216.

Property Owner's Signature

Date

Contractor's Signature

Date

TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1051994

SITÈ NAME:	VASQUEZ BOULEVARD AND I-70
DOCUMENT DATI	E: <u>01/26/2006</u>
Due to one of the	DOCUMENT NOT SCANNED following reasons:
☐ PHOTOGRAPH	IS
☐ 3-DIMENSION	AL
□ OVERSIZED	
☑ AUDIO/VISUAI	L
☐ PERMANENTL	Y BOUND DOCUMENTS
☐ POOR LEGIBIL	_ITY
□ OTHER	
□ NOT AVAILAB	LE ·
	CUMENTS NOT TO BE SCANNED es, Data Validation, Sampling Data, CBI, Chain of Custody)
DOCUMENT DESC	CRIPTION:
3 - DVDs OF PI	ROPERTY VIDEO, PROPERTY #226